

SPA CONTROL ICONS









Operation Notes: TWIN PALMS

*DO NOT TURN 2-WAY DIVERTER VALVES WHILE RELATED PUMP IS OPERATING.

NOTE: MOST JETS CAN BE OPENED OR CLOSED BY TURNING THEM.

HELPFUL TIPS

Suction outlet components have a finite life. The cover/grate should be inspected frequently and replace at least every seven years, or if found to be damaged, broken, cracked, missing, or not securely attached.