

SPA CONTROL ICONS

AC AC Air Controls

2WD 2WD.....2 Way Diverter

O/O ON/OFFWater Feature


Z# (S) Zone

P1 (P1) Pump 1

P2 (P2) Pump 2



SPA CONTROLS ... TREASURE CAY



Operation Notes: TREASURE CAY

*DO NOT TURN 2-WAY DIVERTER VALVES WHILE RELATED PUMP IS OPERATING.

NOTE: MOST JETS CAN BE OPENED OR CLOSED BY TURNING THEM.

HELPFUL TIPS

Suction outlet components have a finite life. The cover/grate should be inspected frequently and replace at least every seven years, or if found to be damaged, broken, cracked, missing, or not securely attached.